

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General							
Zone	Ward No.		Ward Name				
YELAHANKA	11		Kuvempu Nagar				
Street ID	Street Name		Significant Landmark				
W0129, W0062, W0482, W0556, W0550, W0554, W0529, W	NA, 4th Crs, 4th Main Rd, 1st Crs		Naidu layout				
Segment No.	Total Length (m)						
11/S-W0129/S034622	226.22						
Segment Details							
Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	51.15	77.538616	13.070300	77.538463	13.069862	W0482	W0556
2	125.26	77.536809	13.071574	77.537908	13.071227	W0529	W0555
3	20.60	77.545314	13.082565	77.545181	13.082432	W0084	W0121
4	29.21	77.545445	13.082516	77.545346	13.082270	W0084	DEAD END
Work Details							
History of Road / Lane / Circles							
Name of the Work		Sanctioned Estimated Amount (Rs.)			Sanctioned Year		
Road Development and Concrete road work at Naidu layout in Kuvempunagara in ward no 11 (Kuvempunagara) Vidyanarayapura Sub- Division Yelahanka zone		1999000			2015		
Year		Type of Work			Other Work Type		
2015 - 2016		Asphalting					
Tender		Work Details			Job No. / Work Code		
Tender		Road Development and Concrete road work at Naidu layout in Kuvempunagara in ward no 11 (Kuvempunagara) Vidyanarayapura Sub-Division Yelahanka zone			011-15-000038		
Work Order No.		Work Order Date			Period of Extention		
EE/BTP/BBMP/E-PMT/74/2015- 16		06/05/2015			60 DAYS		
Defect Liability Period From		Defect Liability Period To			Multiple road involved with the same Job No/ Work Code #		
27/02/2016		26/02/2017			Yes		
Contractor Details							
Name of Contractor		Contractor Reg No (BBMP/PWD)			Expenditure Booked \ Released (Rs)		
Zone: YELAHANKA		Ward No: 11			Ward Name: Kuvempu Nagar		
					Street ID: W0129, W0062, W0482, W0556, W0550, W		

N KEERTHI

0.00

Phone No.

E-Mail ID

9731567144

Field Inspection Details

Number of Trees

Any Other Information

Name

6

RANGANATH

Date of Inspection

Remarks

18/03/2017

COMPLETED

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA

Ward No: 11

Ward Name: Kuvempu Nagar

Street ID: W0129,
W0062,
W0482,
W0556,
W0558, W0559

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks				
Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAI AH	19/03/2017	17/04/2017	COMPLETED
SE	VASU K M	19/03/2017	17/04/2017	COMPLETED
EE	YARAPPA REDDY	18/03/2017	17/04/2017	COMPLETED
AEE	SHIVAKUMAR	18/03/2017	17/04/2017	COMPLETED
AE	RANGANATH	18/03/2017	17/04/2017	COMPLETED
AE	RANGANATH	18/03/2017	17/04/2017	COMPLETED